

CEE 4674

Embraer 145 Overrun Event at ROA Airport (September 24, 2025)



Dr. Antonio A. Trani
Fall 2025

Pictures of the Overrun



Aircraft used
~180-200 feet of
the EMAS bed

Source: Associated Press

Aircraft probably
entered the EMAS
bed at ~45 knots
(my estimate)



Synopsis of the Accident

“A CommuteAir ERJ-145 operating as United Connection Flight 4339 from KIAD-KROA overran the runway upon landing in wet conditions.”

“The aircraft touched down on runway 34 at KROA but was unable to come to a stop on the runway surface became stuck in the EMAS off the departure end of 34.”

“No injuries were reported out of 53 persons on board.”

AVIATION SAFETY NETWORK
 AN EXCLUSIVE SERVICE OF FLIGHT SAFETY FOUNDATION

[Home](#) | [Database](#) | [Investigation](#) | [Statistics](#) | [Contact us](#) | [About](#) |
 




[Home » ASN Aviation Safety WikiBase](#)

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. You can contribute by [submitting additional or updated information](#).

Date:

Wednesday 24 September 2025

Time:

21:16



Type:

[Embraer ERJ-145XR](#)

Owner/operator:

United Express, opb CommuteAir

Registration:

N21129

MSN:

145703

Year of manufacture:

2003

Fatalities:

Fatalities: 0 / Occupants: 53

Other fatalities:

0

Aircraft damage:

Unknown

Location:

Roanoke-Blacksburg Regional Airport, VA (ROA/KROA) -  [United States of America](#)

Phase:

Landing

Nature:

Passenger - Scheduled

Departure airport:

Washington-Dulles International Airport, DC (IAD/KIAD)

Destination airport:

Roanoke-Blacksburg Regional Airport, VA (ROA/KROA)

Share 0


Post

Source:

<https://asn.flightsafety.org/wikibase/546744>

Evaluation of the Flight Track

Flight parameters prior to touchdown are normal



Ground speed is stable

Descent rate is stable
and within normal
parameters

We do not have the
landing location (very
important)

Source:

<https://www.flightaware.com/live/flight/map/UCA4339/history/20250924/2140Z/KIAD/KROA>

Weather at the Time of the Accident May be a Factor in this Accident

METAR (Meteorological Aerodrome Report):

Incident time: 0117Z:

Wind from the West (260 deg) at 5 knots

- SPECI KROA 250137Z 23005KT 2SM RA BR BKN038 OVC049 22/21 A3006 RMK AO2 SFC VIS 3 RAB07 P0025 T02170211
- SPECI KROA **250112Z** 26005KT **1 3/4SM +RA BR** FEW032 BKN050 OVC085 22/21 A3005 RMK AO2 TWR VIS 2 RAB07 P0000 T02170211

1.75 miles of visibility

Heavy rain

Mist

Source:

<https://asn.flightsafety.org/wikibase/546744>


Runway and EMAS Characteristics

Runway 34 is 5,810 feet long (shortest of two runways at ROA)

Landing Distance Available (LDA) = 5,810 feet

Approach lights (MALSR): 1,400 foot medium intensity approach lighting system with runway alignment indicator lights


EMAS length = 300 feet
EMAS offset is 300 feet



Sources: Airnav and Google Earth

Embraer 145XR and ROA EMAS

Max. Takeoff Weight = 53,000 lbs.
Typical landing weight = 45,000 lbs.
EMAS chart similar to the Bombardier CRJ-200 (53,000 lbs)



The 300-foot EMAS can stop the regional jet while departing the runway at 64 knots
The 300-foot offset provides another 8-10 knots of deceleration before entering the EMAS bed

Reasons for Overruns

In previous accidents aircraft overrun due to following reasons:

- Long landing on a short runway
- Brake failure or degradation
- Incorrect pilot technique
- Failure of thrust reversers
- **Hydroplaning (possible in heavy rain)**

Horne's formula to estimate the minimum dynamic hydroplaning speed

$$V_{hydro} = \sqrt{9P}$$


where:

V_{hydro}	Ground speed (knots)
P	Tire pressure (psi)

Embraer 145 Hydroplaning Speeds

E145X uses tire size 30x9.5-14 main, 19.5x6.75-8 nose
Tire pressures vary from 125 to 140 lb/sq in)

$$V_{hydro} = \sqrt{9P}$$



Source: G.W.H. van Es, Hydroplaning of Modern Aircraft, NLR-TP-2001-242

Figure 2: Experimental hydroplaning speeds as function of tire pressure for different tire types.

Runway Grooving

Transversal grooves are used to carry water away from the runway
Transversal slope is usually 1.5% to dissipate water



Possible Factors in this Accident

- Heavy rainfall rate reported six minutes before the landing
 - Possibility of dynamic hydroplaning
- A long touchdown location on a short runway (5,800 feet)
- Selection of runway 34 instead of runway 24
 - Wind was 260 at 5 knots (favors runway 24)
 - Runway 24 is 6,800 feet long (better margin against an overrun)
 - Runway 34 has an instrument landing procedure (ILS) with 700 feet decision altitude and 1.75 mile visibility
 - Runway 34 has approach lights (1,400 MALSR)
 - Runway 24 has no approach lights (just PAPI lights)
 - Runway 24 has an RNAV (RNP) approach with 500 feet decision altitude and down to 1 mile visibility

Looks like the pilot selected runway 34 because of ILS + approach lights